

## AD 1.5 STATUS OF CERTIFICATION OF AERODROMES

S.N.	Aerodrome Name	ICAO Location Indicator	Certificate Number	Validity of Certificate		Remarks
				From	To	
1	Tribhuvan International Airport, Gauchar, Kathmandu	VNKT	001	03 May 2018	02 May 2019	Aerodrome Reference Point (ARP) 27°41'49.727" N 085°21'28.527"E
2	Biratnagar Airport, Morang	VNVT	002	12 April 2019	11 April 2021	Aerodrome Reference Point (ARP) 26°29'03" N 087°15'52"E

Name of Aerodrome	Exemption	Exemption granted up to
Tribhuvan International Airport (VNKT)	1. RESA not provided at both the ends of runway.	02 May 2020
	2. The extent of runway strip beyond runway 20 end and its width does not comply to the requirements set forth in Civil Aviation Requirement (CAR) – 14, part 1.	02 May 2019
	3. Operation of TIA with inadequate separation between runway and parallel taxiway.	02 May 2019
Biratnagar Airport (VNVT)	1. Operation of Biratnagar airport with inadequate separation between runway and parallel taxiway.	10 years
	2. The width of runway strip is not as per CAR – 14, Part-I. <ul style="list-style-type: none"> <li>• Required 150m either side from the center line of the runway.</li> <li>• Available runway strip at runway 27: NE 106m; SE 94m.</li> <li>• Available runway strip at runway 09: SW 75m.</li> </ul>	10 years