

Pre-flight Information Bulletin	CIVIL AVIATION AUTHORITY OF NEPAL AIM DEPARTMENT INTERNATIONAL NOTAM OFFICE TIA, KATHMANDU Tel: +977-01-4113315, Fax: 01-4113178 E-mail: notamtia@gmail.com	Date and time of issue 15/11/2025 0000 UTC	Route and Area Coverage 1) KATHMANDU FIR (VNSM) AND OTHER FIRS 2) VNKT/B345/LLK/R460/L626/DPN/G336/SMR/G590/IID/W10/BBB 3) VNKT/R325/R344/CEA/BGO/G463/L507/BKK
GENERAL (FIR/ Routes/ Aerodromes)			
LOCATION	FACILITY	INFORMATION	
<u>KATHMANDU</u> VNBW VNBW VNKT VNKT VNKT VNST VNJS	ATIS STRIP ATIS BAY TURNING BAY ARFF LGT	A0221/25: AITS ON FREQ 128. 050 MHZ U/S DUE TECR. FM 2511130415 TL 2511270415. A0220/25: 0015-1215 DAILY MAINTENANCE WIP ON RWY STRIP BEYOND 60M FROM RWY EDGE PILOTS TO TAKE CTN WHILE LDG/TAOF.FM 2511130015 TL2511191215. A0219/25: AITS ON FREQ 127.0 MHZ U/S DUE TECR. FM 2511111350 TL 2511211340. A0210/25: ACFT STAND BAY-3 CLSD DUE MAINT PILOT TAKE CAUTION WHILE TAXING. FM 2511010325 TL 2601142359. A0190/25: SIZE OF RWY TURNING BAY LOCATED AT THE EXTREME SOUTHERN END OF RWY02 IS TEMPO DECREASED BY 11M DUE TO CONST WIP. 1. MINIMUM STEERING ANGLE IS LIMITED TO 40 DEGREE AND MAX TAX SPEED IS LIMITED TO 10KT. 2. BLUE REFLECTORS ARE PROVIDED IN PLACE OF TURNING BAY LGT. FM 2509150955 TL 2512142359. D0156/25: FIREFIGHTING AND RESCUE FACILITY NOT AVBL DUE FIRE VEHICLE U/S. FM 2511090615 TL 2511201215. D0153/25: THR LGT WBAR RWY24 AND RWY END LGT RWY06 U/S DUE TECR. FM 2510300350 TL 2511150645.	
<u>DELHI FIR</u> VIDP VIDP VIDP VIDP VIDP	RWY RWY RWY PRO ILS	A2872/25: 1830-2330 ON MON FRI RWY 11R/29L NOT AVBL FOR OPS DUE MAINT. FM 2511031830 TL 2511282330. A2871/25: 1830-2330 ON WED AND 2131-2330 ON SUN, RWY 10/28 NOT AVBL FOR OPS DUE MAINT. FM 2511121830 TL 2511302330. A2770/25: 1830-2330 ON THU AND 1830-2130 ON SUN, RWY 11L/29R NOT AVBL FOR OPS DUE MAINT. FM 2511021830 TL 2511302130. A2395/25: NOISE ABATEMENT PROCEDURES NOT ADHERED DUE TO UNAVAILABILITY OF ILS PROCEDURES FOR RWY 10/28. FM 2509250441 TL 2511271130. G1032/25: ILS (CAT-II/IIIA/IIIB) RWY 28 PROC IS TEMPO WITHDRAWN DUE EQPT REPLACEMENT.FM 2510071218 TL 2512312359EST.	
<u>MUMBAI FIR</u> <u>KOLKATA FIR</u> VECC <u>CHENNAI FIR</u> <u>DHAKA FIR</u> VGHS	ILS NDB	G0875/25: ILS RWY 19L CAT-II IDENT IDUM (LOC 110.300MHZ, GP 335.000MHZ, DME ILS 19L CH40X) NOT AVBL DUE EQPT REPLACEMENT. FM 25098270536 TL 2511272359EST. A0437/24: NDB FREQ 298 KHZ INDENT 'DCN' TRANSMISSION U/S DUE ANTENNA UNAVAILABILITY FM 2411170500 TL PERM.	
<u>YANGON FIR</u> <u>BANGKOK FIR</u> VTBS VTBD VTBD <u>KUNMING FIR</u> ZPPP ZUUU ZUUU	RWY RWY RWY RWY SID PROC AD	A3218/25: 2030-2145 ON 15 NOV RWY 01/19 CLSD DUE TO WIP. A3175/25: 1600-2200 ON 13 14 17 20 AND 21 NOV RWY03L/21R CLSD DUE TO WIP. A3117/25: 1600-2200 ON 09 12 15 16, 1500-1600 14 NOV RWY03R/21L CLSD DUE TO WIP. U5336/25: 1800-2030 ON 13 15 AND 16 NOV RWY04/22 CLSD DUE TO MAINT. U4788/25: 1. SID RWY02R(ZUUU-3V-2): SEGMENT JITANG VOR/DME 'JTG' -GURET OF PROCEDURE... FM 2510161600 TL 2604301559. (DETAILS SEE IN NOTAM...) U4573/25: AD NOT AVBL FOR ALTN OF PASSENGER FLIGHT FM HONGKONG CHINA, MACAO CHINA, TAIWAN CHINA, AND NOT AVBL FOR INTERNATIONAL PASSENGER FLIGHT ALTN, EXCEPT EMERGENCY OR THE DESTINATION AIRPORT IS CHENGDU/TIANFU. FM 2509280923 TL 2603311559.	

<u>KOLKATA FIR</u> <u>DHAKA FIR</u> G.1 G.2	<u>02-30/11</u> 0000-1600 <u>02-30/11</u> 0000-1600	A402/A0400/A0398/25: 0000-1600 EXC FRI AND SAT, BANGLADESH NAVY SHIPS WILL CARRY OUT FRNG PRACTICE WI THE AREA VGD-35, VGD-33 AND VGD 30. A0401/A0399/25: 0000-1600 EXC FRI AND SAT, BANGLADESH NAVY SHIPS WILL CARRY OUT FRNG PRACTICE WI THE AREA VGD-34 AND VGD 32.	<u>FL100</u> SFC <u>FL400</u> SFC
<u>YANGON FIR</u> <u>BANGKOK FIR</u> <u>KUNMING FIR</u> <u>GUANGZHOU FIR</u>			